



*3al-service.ru*

Pos.	P/N	Description	Q.ty	K1	K2	K3	K4
1	10.3073.08	O-ring, 1,78x23,52 mm Ni 85	2	*			10
2	10.3060.00	O-ring, 1,78x12,42 mm	2	*			10
3	10.4165.00	Back-up ring,	1	*			3
4	10.4060.00	Back-up ring, 22x24x2 mm	1	*			10
5	60.2803.51	Sst seat, 10 mm	1	*			5
6	10.3064.01	O-ring, 1,78x14 mm Ni 85	1	*			10
9	60.2816.21	Shutter pin, M8 +ball, 1/2"	1	*			5
10	60.2806.31	9 mm brass piston ring	1				5
11	10.3058.01	O-ring, 1,78x10,82 mm	1	*			10
12	10.4061.00	Back-up ring, 9x11x2 mm	1	*			10
13	10.3070.02	O-ring, 1,78x18,77 mm Ni 85	1	*			10
14	60.2807.31	9x26,9 mm brass piston ring	1				5
15	60.2802.51	Sst pin	1				5
16	60.2808.31	10,7 mm brass piston ring	1				5
17	60.2810.31	Lower plug, brass	1				3
18	15.1021.00	Roll pin, 3x14 mm Sst.	1				10
19	60.2804.31	Piston holder, brass	1				5
20	30.0728.84	Bushing, 9x13x6 mm plast. black	1	*			10
21	60.2813.51	Sst. valve piston	1				5

Pos.	P/N	Description	Q.ty	K1	K2	K3	K4
22	10.3068.01	O-ring, 1,78x17,17 mm Ni 85	1	*			10
23	10.4161.00	Back-up ring, 18 mm	1	*			3
24	10.3072.60	O-ring, 1,78x21,95 mm Ni 85	1	*			10
25	10.4162.00	Back-up ring, 14,2 mm	1	*			3
26	10.3057.00	O-ring, 1,78x9,25 mm	1	*			10
27	16.2203.00	Set screw, DIN915 M6x10 mm Sst.	1				10
28	60.2805.35	Housing -VB80/280 Zero,1/2Bsp F bras.	1				3
29	60.2801.51	Sst shutter	1				5
30	60.2812.51	Sst spring, 1,5x12,5x32 mm	1				10
31	60.2809.31	Shutter coupl., 1/2F Bsp brass	1				3
33	11.4589.10	Hex. locknut, M8	1				10
35	60.0148.24	Knob + Plug -PulsarRv	1				5
36	14.3720.40	Washer, 9,2x24x0,5 mm	1				10
37	11.4573.31	Hex. nut, M8, brass	2				10
38	60.0033.61	Spring, 5,7x26x53 mm blue	1				5
40	60.2624.31	Nozzle, 4,5 mm brass x1/2 Bsp **	1				10
40	60.2625.31	Nozzle, 5,5 mm brass x 1/2 Bsp **	1				10
50	10.4407.00	Seal frame >VB60-80 zero **	1				1
51	10.4408.00	Seal frame >VB60-80 zero **	1				1

\*\* On request

Kit	P/N	Description	
K1	60.2814.24	Spares kit -VB80/280.Zero, 16x1pcs.	1