


60.5000.00 VB200/150 unload. 1"F Npt
 60.5000.15 VB200/150 unload. 1"F Bsp
 60.5020.00 VB200/150 unload. 1"F Npt +handwheel

60.5020.15 VB200/150 unldr 1"F Bsp +hand wheel
 60.5025.00 VB200/70 unldr valve, 1" Npt
 60.5025.15 VB200/70 unldr valve, 1" Bsp FF



Поз	Артикул	Описание	Коли	K1	K2	K3	K4
1	60.5014.31	Shutter coupl., 1"Npt F brass	1				3
1	60.5026.31	Coupling, 1"Bsp F brass (1,2)	1				3
2	10.3206.01	O-ring, 2,62x28,25 mm	2	*			10
3	60.5013.51	Spring, 1,3x18x29 mm Sst.	1				10
4	60.5012.99	Shutter pin, brass+or 5,33x12,06 mm N	1				2
5	10.3314.00	O-ring, 5,33x12,06 mm	1	*			10
6	60.5001.35	Housing-VB200/60-150, 1"Npt brass	1				1
6	60.5024.35	Hous.-VB200/150-1"Bsp FF (1,2)	1				1
7	10.3072.01	O-ring, 1,78x20,35 mm Ni 85	1	*			10
8	60.5002.51	Seat, 15,8x23x6 mm Sst.	1	*			2
9	60.5003.51	Shutter pin, M8 Sst.	1	*			3
10	10.3195.01	O-ring, 2,62x20,29 mm Ni 90	1	*			10
11	60.5010.31	Reduction bushing, brass	1				2
12	10.4080.00	Back-up ring, 12x18,2x2 mm	1	*			10

Поз	Артикул	Описание	Коли	K1	K2	K3	K4
13	10.3234.00	O-ring, 3,53x10,69 mm	1	*			10
14	60.5009.31	Piston holder, brass	1				1
15	60.5011.61	Valve regulating screw, M10x44 z.pl. (3)	1				3
16	11.4629.00	Hex. nut, M10	1				10
17	60.5008.31	Upper plug, M10 brass	1				1
18	60.5005.31	Spring guide spacer, brass	1				1
19	60.5006.61	Spring, 6x30x62 mm	1				5
19	60.5031.61	Spring 5x23x62 mm (4,2)	1				1
20	60.5007.31	Spring guide spacer, brass	1				3
21	14.7461.00	Ball, 13/32" Sst.	1				10
22	10.4081.00	Back-up ring, 15,8x22x2 mm	1	*			10
23	10.3237.00	O-ring, 3,53x15,47 mm	1	*			10
24	60.5004.51	Piston, M8 Sst.	1				2
25	60.5021.22	Handwheel, 70mm -M10x44 (5,6)	1				2

КМТ	Артикул	Описание	Коли
K1	60.5016.24	Spares kit -VB200/150, 10x1pcs.	1

(1) 60.5000.15 (2) 60.5025.15 (3) 60.5000.00 (4) 60.5025.00 (5) 60.5020.00 (6) 60.5020.15