



3al-service.ru

| Pos. | P/N | Description | Q.ty | K1 |
|------|------------|-------------------------------------|------|----|
| 1 | 60.8003.31 | Plug, M38x1 brass | 1 | |
| 2 | 10.4089.00 | Back-up ring, 32,7x35,5x1,5 mm | 1 | * |
| 3 | 10.3078.08 | O-ring, 1,78x31,45 mm Ni 85 | 1 | * |
| 4 | 10.3058.02 | O-ring, 1,78x10,82 mm Ni 85 | 1 | * |
| 5 | 10.4090.00 | Back-up ring, 11,2x14x1,5 mm | 1 | * |
| 6 | 10.3077.28 | O-ring, 1,78x29,87 mm Ni 85 | 1 | * |
| 7 | 10.4088.00 | Back-up ring, 31,2x34x1,5 mm | 1 | * |
| 8 | 60.8012.51 | Spacer ring, 14,5x34x27,5 mm Sst. | 1 | |
| 9 | 60.8016.31 | Spacer ring, 5,2x19x12,5 mm brass | 1 | |
| 10 | 60.8022.51 | Piston, 5x43,8 mm Sst. | 1 | |
| 11 | 60.8004.51 | Spring, 3,5x17,5x29 mm Sst. | 1 | |
| 12 | 60.8013.31 | Seat holding spacer, brass | 1 | |
| 13 | 60.8015.51 | Seat, 3x14x7,5 mm Sst. | 1 | * |
| 14 | 14.7418.71 | Ball, 5/32" | 1 | * |
| 15 | 60.8014.51 | Ball holding piston, Sst. | 1 | |
| 16 | 60.8006.51 | Spring, 1x7,2x14 mm Sst. | 1 | |
| 17 | 11.4574.11 | Hex. nut, M8, Sst. | 1 | |
| 18 | 60.8023.24 | Seat, 14mm Sst. + shutter pin, Sst. | 1 | * |
| 19 | 10.4085.00 | Back-up ring, 29,2x32 mm | 1 | * |
| 20 | 10.3077.08 | O-ring, 1,78x28,3 mm Ni 85 | 1 | * |
| 21 | 60.8011.31 | Spacer ring | 1 | |
| 22 | 60.8002.51 | Piston, M8-M10 Sst. | 1 | |
| 23 | 10.4086.00 | Back-up ring, 6,3x8,5x1,5 mm | 1 | * |

| Pos. | P/N | Description | Q.ty | K1 |
|------|------------|-------------------------------------|------|----|
| 24 | 10.3018.08 | O-ring, 1,5x6 mm Ni 85 | 1 | * |
| 25 | 10.4094.00 | Back-up ring, 15,5x20x5 mm | 2 | * |
| 26 | 10.3180.08 | O-ring, 2,62x15,08 mm Ni 85 | 1 | * |
| 27 | 10.4087.00 | Back-up ring, 23,5x26,5x2,5 mm | 1 | * |
| 28 | 10.3073.08 | O-ring, 1,78x23,52 mm Ni 85 | 1 | * |
| 29 | 60.8010.51 | Spacer ring, 12,2x26,5x33,5 mm Sst. | 1 | |
| 30 | 10.2012.00 | Stem seal, 12x19x2,8 mm +O-ring | 1 | * |
| 31 | 60.8001.35 | Housing -VB16, 1/2F Bsp brass | 1 | |
| 32 | 60.0022.31 | Grub screw, brass 1/4 Bsp | 1 | |
| 33 | 11.6500.09 | Plate, 10,9x1,5 mm Cu | 1 | |
| 34 | 60.8005.61 | Spring, 7x42,5x48 mm z.pl. | 1 | |
| 35 | 60.8017.31 | Spring guiding washer, brass | 1 | |
| 36 | 60.8018.61 | Valve regulating nut, M10 z.pl. | 1 | |
| 37 | 15.1042.00 | Roll pin, 3x26 mm Sst. | 1 | |
| 38 | 10.4091.00 | Back-up ring, 21,2x24x1,5 mm | 1 | * |
| 39 | 10.3072.01 | O-ring, 1,78x20,35 mm Ni 85 | 1 | * |
| 40 | 60.8019.51 | Shutter seat, Sst. | 1 | |
| 41 | 10.3292.08 | O-ring, 4x8 mm Ni 85 | 1 | * |
| 42 | 60.8020.51 | Pin, hex.17 Sst | 1 | |
| 43 | 60.8007.51 | Spring, 0,8x12,2x27 mm Sst. | 1 | |
| 44 | 10.3072.60 | O-ring, 1,78x21,95 mm Ni 85 | 1 | * |
| 45 | 10.4092.00 | Back-up ring, 22,7x25,5x1,5 mm | 1 | * |
| 46 | 60.8021.31 | Shutter coupl., 1/2F Bsp brass | 1 | |

| Kit | P/N | Description | Q.ty | K1 |
|-----|------------|-----------------------------|------|----|
| K1 | 60.8025.24 | Spares kit -VB16, 24x1 pcs. | 1 | |